

Location of Pipe Break  
48.401457 N, 103.63923 W




**Legend**

- Monitoring Well
- 24 Hour Pumping Location
- Interceptor Trench
- Dam Location
- Natural Gas Line
- Phone Line
- Water Extraction Point
- Boom
- Containment Berm
- Line Break Baracade
- Extent of Excavation - 01/24
- Extent of Visual Impacts - 01/26
- Existing Natural Dam Location
- Blacktail Creek
- Existing Pipeline

- Notes**
1. Coordinate System: GCS North American 1983
  2. 2014 National Agriculture Imagery Program (NAIP) aerial orthoimagery provided by USDA's Farm Service Agency
  3. Existing Pipeline System provided by Summit Midstream

Disclaimer: Stantec assumes no responsibility for data supplied in electronic format. The recipient accepts full responsibility for verifying the accuracy and completeness of the data. The recipient releases Stantec, its officers, employees, consultants and agents, from any and all claims arising in any way from the content or provision of the data.



Project Location: Williams County, North Dakota  
 Prepared by LMB on 2015-02-07  
 Technical Reviewed by JR on 2015-02-07

Client/Project: Meadowlark Midstream Company, LLC  
 Blacktail Creek

Figure No. 5

Title: Control Measures - 2/7/2015

E:\Blacktail\mxd\NewMapA\Figure 5 - Control Measures\Figure5\_Control\_Measures\_02072015.mxd  
 Revised: 2015-02-08 By: Blackman